

CERTIFICATE

Factory Inspection

The certified products are manufactured in a proper and consistent quality.
The applied quality procedures are found to be adequate for their intended use and documented appropriate.

Factory:

Kostal Industry Electric GmbH

Lange Eck 11
58099 Hagen
Germany

Certified products:

Solar Inverters

The factory is subject to an annual production inspection by Primara Test- und Zertifizier-GmbH according to DIN EN ISO/IEC 17067:2013 and their requirements and procedures.

Kaufbeuren, July 2018

Certification department

